



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 4DRBUAAP76B247927	Model Year 2006	License # TEMP	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 4DRBRAAP84B963377	Model Year 2004	License # Temp	Rated Capacity ***** 60
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Conley Transportation Inc		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 4DRBUAAP36B247925	Model Year 2006	License # TEMP	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 4DRBUAAP16B247924	Model Year 2006	License # TEMP	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 4DRBUAAPX6B250580	Model Year 2006	License # TEMP	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1VBBAAP81H413947	Model Year 2001	License # 9657	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP3TH369956	Model Year 1996	License # A118	Rated Capacity ***** 71
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Conley Transportation Inc		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 4DRBUAAP56B247926	Model Year 2006	License # TEMP	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBADR6X1088510	Model Year 1999	License # R935	Rated Capacity ***** 84
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Conley Transportation Inc		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBABP3TH369907	Model Year 1996	License # M234	Rated Capacity ***** 71
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Conley Transportation Inc		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XORBUAAP55B975986	Model Year 2005	License # 4170	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XXDSE35P34HB10478	Model Year 2004	License # 4044	Rated Capacity ***** 15
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDSE35P54HB10479	Model Year 2004	License # 4045	Rated Capacity ***** 15
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 4468	Model Year 2005	License # 122	Rated Capacity ***** 53
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDSE35P54HB10482	Model Year 2004	License # 4048	Rated Capacity ***** 15
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDSE35P34HB10481	Model Year 2004	License # 4047	Rated Capacity ***** 15
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XXDSE35P14HB10480	Model Year 2004	License # 4046	Rated Capacity ***** 15
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XORB4AAP95B975988	Model Year 2005	License # 4172	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number ADRBUAAP358975985	Model Year 2005	License # 4169	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDSE35P74AB10483	Model Year 2004	License # 4049	Rated Capacity ***** 15
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number X0RBUAAP55B975986	Model Year 2005	License # 4170	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XORBUAAP75B975990	Model Year 2005	License # 4174	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XORBUAAP05B975989	Model Year 2005	License # 4173	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XORBRAAP14B961454	Model Year 2004	License # H166	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XORBRAAP54B962655	Model Year 2004	License # H168	Rated Capacity ***** 65
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XORBUAAP75B975987	Model Year 2005	License # 4171	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XORBRAAP84B961452	Model Year 2004	License # H164	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XORBRAAPX4B961453	Model Year 2004	License # H165	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 0454	Model Year 2004	License # H166	Rated Capacity ***** 71
Chassis Make International	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP62H542187	Model Year 2002	License # 5187	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAMXWH558131	Model Year 1998	License # H927	Rated Capacity ***** 42
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Conley Transportation Inc		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XORBRAAP34B961455	Model Year 2004	License # H167	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP42H542186	Model Year 2002	License # 5186	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP02H542184	Model Year 2002	License # 5184	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP22H542185	Model Year 2002	License # 5185	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP1TH287997	Model Year 1996	License # 1837	Rated Capacity ***** 72
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP82H542188	Model Year 2002	License # 5188	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAPX2H542189	Model Year 2002	License # 5189	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBNEP3LH275139	Model Year 1990	License # 1815	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XXDWE35F01HB16548	Model Year 2001	License # 9543	Rated Capacity ***** 14
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAPW1H413946	Model Year 2001	License # 9656	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XXDWE35F81HB10979	Model Year 2000	License # 9542	Rated Capacity ***** 20
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP41H413945	Model Year 2001	License # 9655	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBNEP3LH275142	Model Year 1990	License # 1818	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDSE35F41HB65749	Model Year 2001	License # 9141	Rated Capacity ***** 20
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XXDSE35F21HB65748	Model Year 2001	License # 9140	Rated Capacity ***** 20
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBPEP1PH511434	Model Year 1993	License # 1835	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBNMP6NH418850	Model Year 1992	License # 1831	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDSE37F9XAB39010	Model Year 1999	License # 1337	Rated Capacity ***** 15
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XXDSE37F0XHB39011	Model Year 1999	License # 1338	Rated Capacity ***** 15
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBNMP6NH418847	Model Year 1992	License # 1828	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBNMP8NH418848	Model Year 1992	License # 1829	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBNNMPXNH418849	Model Year 1992	License # 1830	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLPCFM4KH678477	Model Year 1989	License # 1814	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XXDSE37F7XHB58588	Model Year 1999	License # 1339	Rated Capacity ***** 15
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAM8WH558712	Model Year 1998	License # 1843	Rated Capacity ***** 16
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLPCFM9KH678474	Model Year 1989	License # 1811	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLACFM0KH678475	Model Year 1989	License # 1812	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLPCFM2KH678476	Model Year 1989	License # 1813	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDJE37F3THA18110	Model Year 1996	License # 1930	Rated Capacity ***** 18
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDJE37F7THA18112	Model Year 1996	License # 1931	Rated Capacity ***** 18
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLPCFM7KH618473	Model Year 1989	License # 1810	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP5TH287999	Model Year 1996	License # 1839	Rated Capacity ***** 71
Chassis Make Thomas	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HV5BAAP6TH288000	Model Year 1996	License # 1840	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDJE37F5THA18108	Model Year 1996	License # 1929	Rated Capacity ***** 18
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDJE37MHPHA27065	Model Year 1993	License # 1924	Rated Capacity ***** 20
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAM8VH477319	Model Year 1997	License # 1841	Rated Capacity ***** 53
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP1VH477320	Model Year 1997	License # 1842	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBNEP1LH275141	Model Year 1990	License # 1817	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBNEP5LH275143	Model Year 1990	License # 1819	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDJE37M7RHA35919	Model Year 1994	License # 1923	Rated Capacity ***** 20
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number X1VLPHYM6HH485119	Model Year 1987	License # 1802	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLPHYM2HH485120	Model Year 1987	License # 1803	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBNEPXLH275140	Model Year 1990	License # 1816	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XHVLPHYM9HH485115	Model Year 1987	License # C898	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XXXVPHYM0HH485116	Model Year 1987	License # C899	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XXVLPHYM4HH485118	Model Year 1987	License # 1801	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLPHYM3HH485112	Model Year 1987	License # c895	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XXVLPHYM5HH485113	Model Year 1987	License # c896	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XXVLPHYM7HH485114	Model Year 1987	License # C897	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLPCFM7JH583247	Model Year 1988	License # 1808	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLPCFM0JH583249	Model Year 1988	License # 1806	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBPP3M1PH473533	Model Year 1993	License # 1832	Rated Capacity ***** 19
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBNEP8MH332985	Model Year 1990	License # 1821	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBNEPXMH332986	Model Year 1990	License # 1822	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLPCFM5JH583246	Model Year 1988	License # 1809	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP6WH612955	Model Year 1998	License # 1845	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP8WH612956	Model Year 1998	License # 1846	Rated Capacity ***** 71
Chassis Make Thomas	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBNEP6MH332984	Model Year 1990	License # 1820	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBNNMM5MH392505	Model Year 1991	License # 1824	Rated Capacity ***** 19
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBNNMP8MH392508	Model Year 1991	License # 1827	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP4WH612954	Model Year 1988	License # 1844	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XXDSE37F9WHA32411	Model Year 1988	License # 1935	Rated Capacity ***** 17
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XXXDSE37F0WA32412	Model Year 1998	License # 1336	Rated Capacity ***** 17
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBNNMM3MH392504	Model Year 1991	License # 1823	Rated Capacity ***** 19
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDJE37F3VHA81971	Model Year 1997	License # 1934	Rated Capacity ***** 18
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDJE37MZRHA62056	Model Year 1994	License # 1927	Rated Capacity ***** 27
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDJE37M4RHA62057	Model Year 1994	License # 1928	Rated Capacity ***** 13
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBPEP3PH511435	Model Year 1993	License # 1836	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFDJE37F5VHA81969	Model Year 1997	License # 1932	Rated Capacity ***** 18
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number XFCJE37F1VHA81970	Model Year 1997	License # 1933	Rated Capacity ***** 18
Chassis Make Ford	Body Make Collins	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLPHYM31HHA1034	Model Year 1987	License # C887	Rated Capacity ***** 16
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBPP3P8PH511432	Model Year 1993	License # 1833	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBPEXP511433	Model Year 1993	License # 1834	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLPHYM8HHA10798	Model Year 1987	License # C892	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLPHYM7HHA10808	Model Year 1987	License # C890	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVLPHYMZHH10988	Model Year 1987	License # C893	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP1XH240572	Model Year 2000	License # 1852	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP3XH240573	Model Year 1999	License # 1853	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAP21H413944	Model Year 2001	License # 9654	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAM7XH240467	Model Year 1999	License # 1847	Rated Capacity ***** 48
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP8XH240570	Model Year 1999	License # 1850	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Missoula Co Public Schls	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAPXXH240571	Model Year 1999	License # 1851	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GBKH32K1R3309025	Model Year 1994	License # 9094	Rated Capacity ***** 14
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL7T1BOYJ525586	Model Year 2001	License # H107	Rated Capacity ***** 71
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL7T1B6YJ525933	Model Year 2001	License # H105	Rated Capacity ***** 71
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL7T1B1YJ525905	Model Year 2001	License # H106	Rated Capacity ***** 71
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL7T1P4TJ515888	Model Year 1997	License # 1511	Rated Capacity ***** 65
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL7T1P7TJ515643	Model Year 1997	License # 2085	Rated Capacity ***** 65
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL7T1B1YJ525791	Model Year 2001	License # H108	Rated Capacity ***** 71
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GBL7T1D2YJ504314	Model Year 2000	License # 9600	Rated Capacity ***** 72
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL7T1P4RJ518430	Model Year 1994	License # C621	Rated Capacity ***** 66
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL7T1P5TJ515589	Model Year 1997	License # 1512	Rated Capacity ***** 65
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL7T1P8SJ502026	Model Year 1995	License # 9597	Rated Capacity ***** 71
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GBL7T1D8YJ504026	Model Year 2000	License # 9598	Rated Capacity ***** 72
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GBL7T1D4YJ504122	Model Year 2000	License # 9595	Rated Capacity ***** 72
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number IGDJ6P1P1MV500499	Model Year 1991	License # 9593	Rated Capacity ***** 71
Chassis Make GMC	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDJ6P1P4MV500500	Model Year 1991	License # C623	Rated Capacity ***** 71
Chassis Make GMC	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL7T1P4SJ501875	Model Year 1995	License # 9599	Rated Capacity ***** 71
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL7T1P0PJ650081	Model Year 1993	License # 9596	Rated Capacity ***** 71
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GBL6P1P1MV100279	Model Year 1990	License # C620	Rated Capacity ***** 71
Chassis Make Chevrolet	Body Make Wayne	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Hellgate Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GBL6P1PXMV100281	Model Year 1990	License # C622	Rated Capacity ***** 71
Chassis Make Chevrolet	Body Make Wayne	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Hellgate Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Lolo Elementary	
Vehicle I.D. # (VIN) - Entire Number 1BAAECSH4WF077500	Model Year 1998	License # 654	Rated Capacity ***** 66
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Lolo Elementary	
Vehicle I.D. # (VIN) - Entire Number 1BAANCSH5RF059995	Model Year 1994	License # 994	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Lolo Elementary	
Vehicle I.D. # (VIN) - Entire Number 8108	Model Year 1996	License # 1929	Rated Capacity ***** 18
Chassis Make Ford	Body Make Carpenter	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Potomac Elementary	
Vehicle I.D. # (VIN) - Entire Number 1HVBABP7SH598184	Model Year 1995	License # AU96	Rated Capacity ***** 65
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Majestic Bus Service, Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Potomac Elementary	
Vehicle I.D. # (VIN) - Entire Number 1HVBABP9SH598185	Model Year 1995	License # AU94	Rated Capacity ***** 65
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Majestic Bus Service, Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Potomac Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDJ6P1F5GV520069	Model Year 1986	License # L201	Rated Capacity ***** 66
Chassis Make GMC	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Majestic Travels Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Bonner Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL6P1FXJY517250	Model Year 1988	License # L181	Rated Capacity ***** 72
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Majestic Travels Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Bonner Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL6P1FXMV501747	Model Year 1991	License # BQ3	Rated Capacity ***** 71
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Majestic Travels Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Bonner Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL6P1FXMV501845	Model Year 1991	License # T89	Rated Capacity ***** 71
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Majestic Bus Service, Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Bonner Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL6P1F3JV517266	Model Year 1988	License # L204	Rated Capacity ***** 72
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Majestic Travels Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Bonner Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL6P1F6MX501762	Model Year 1991	License # T88	Rated Capacity ***** 71
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: L & B Busing, Inc		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Bonner Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL6P1FXMY501764	Model Year 1991	License # BQ2	Rated Capacity ***** 71
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Majestic Travels Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Bonner Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDJ6P1F6GV520078	Model Year 1986	License # L206	Rated Capacity ***** 66
Chassis Make GMC	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Majestic Travels Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Bonner Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL6P1FXIV517247	Model Year 1988	License # L209	Rated Capacity ***** 72
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Majestic Travels Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Bonner Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDL6P1F1MV501846	Model Year 1991	License # T86	Rated Capacity ***** 71
Chassis Make GMC	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Majestic Travels Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Woodman Elementary	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP81H413947	Model Year 2001	License # 9657	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Woodman Elementary	
Vehicle I.D. # (VIN) - Entire Number XORBRAAP34B961455	Model Year 2004	License # H167	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name DeSmet Elementary	
Vehicle I.D. # (VIN) - Entire Number 4DRBUAAP95B975988	Model Year 2005	License # 4172	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name DeSmet Elementary	
Vehicle I.D. # (VIN) - Entire Number 1434	Model Year 1993	License # 1835	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name DeSmet Elementary	
Vehicle I.D. # (VIN) - Entire Number X4DRBUAAP95897998	Model Year 1996	License # 1838	Rated Capacity ***** 71
Chassis Make Thomas	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name DeSmet Elementary	
Vehicle I.D. # (VIN) - Entire Number ADRBUAAP358975985	Model Year 2005	License # 4169	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Target Range Elementary	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAPXXH240568	Model Year 1999	License # 1848	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Target Range Elementary	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAP1XH240569	Model Year 1999	License # 1849	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Target Range Elementary	
Vehicle I.D. # (VIN) - Entire Number XXXXXXXXXXXX5989	Model Year 2005	License # 4173	Rated Capacity ***** 71
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Beach Transportation		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Clinton Elementary	
Vehicle I.D. # (VIN) - Entire Number XXXXXXXXXXXX8623	Model Year 1990	License # C274	Rated Capacity ***** 72
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Roy Handley		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Clinton Elementary	
Vehicle I.D. # (VIN) - Entire Number XXXXXXXXXXXX5457	Model Year 2000	License # C276	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Roy Handley		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Clinton Elementary	
Vehicle I.D. # (VIN) - Entire Number XXXXXXXXXXXX1982	Model Year 1995	License # C272	Rated Capacity ***** 72
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Roy Handley		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Clinton Elementary	
Vehicle I.D. # (VIN) - Entire Number XXXXXXXXXXXX3917	Model Year 1997	License # C271	Rated Capacity ***** 72
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Roy Handley		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Clinton Elementary	
Vehicle I.D. # (VIN) - Entire Number XXXXXXXXXXXX6303	Model Year 1992	License # C273	Rated Capacity ***** 54
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Roy Handley		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Swan Valley Elementary	
Vehicle I.D. # (VIN) - Entire Number 9907	Model Year 1996	License # M234	Rated Capacity ***** 71
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Swan Valley Elementary	
Vehicle I.D. # (VIN) - Entire Number 8510	Model Year 1986	License # R935	Rated Capacity ***** 84
Chassis Make Thomas	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Conley Transportation Inc		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Swan Valley Elementary	
Vehicle I.D. # (VIN) - Entire Number 9956	Model Year 1996	License # A118	Rated Capacity ***** 71
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Conley Transportation Inc		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Swan Valley Elementary	
Vehicle I.D. # (VIN) - Entire Number 8131	Model Year 1998	License # H927	Rated Capacity ***** 42
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Conley Transportation Inc		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Swan Valley Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GDJ6P1B9EV528962	Model Year 1984	License # H931	Rated Capacity ***** 59
Chassis Make GMC	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Conley Transportation Inc		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Swan Valley Elementary	
Vehicle I.D. # (VIN) - Entire Number X1GDJ6P1BKVS01069	Model Year 1989	License # H928	Rated Capacity ***** 59
Chassis Make GMC	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Conley Transportation Inc		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Swan Valley Elementary	
Vehicle I.D. # (VIN) - Entire Number 2379	Model Year 1989	License # H929	Rated Capacity ***** 71
Chassis Make Chevrolet	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Conley Transportation Inc		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Swan Valley Elementary	
Vehicle I.D. # (VIN) - Entire Number X1GTK6P1BGV538703	Model Year 1986	License # H930	Rated Capacity ***** 59
Chassis Make GMC	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Conley Transportation Inc		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Seeley Lake Elementary	
Vehicle I.D. # (VIN) - Entire Number XXXXXXXXXXXX2274	Model Year 1986	License # C311	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Diane's Buses		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Seeley Lake Elementary	
Vehicle I.D. # (VIN) - Entire Number XXXXXXXXXXXXX5133	Model Year 1986	License # C309	Rated Capacity ***** 71
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Diane's Buses		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Seeley Lake Elementary	
Vehicle I.D. # (VIN) - Entire Number XXXXXXXXXXXX9552	Model Year 1985	License # C310	Rated Capacity ***** 65
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Diane's Buses		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBVAAR85A975002	Model Year 2004	License # 409	Rated Capacity ***** 83
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABNBXA45F219191	Model Year 2005	License # 795	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABNCKA16F232222	Model Year 2005	License # 4775	Rated Capacity ***** 83
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABNC0H04F215716	Model Year 2004	License # 612	Rated Capacity ***** 83
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBL7T1J0VJ115320	Model Year 1997	License # 1469	Rated Capacity ***** 57
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBVAARX5A975003	Model Year 2004	License # 540	Rated Capacity ***** 83
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAHCPH63F207000	Model Year 2003	License # 494	Rated Capacity ***** 72
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANCPA84F212907	Model Year 2004	License # 1244	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABNC0H24F215717	Model Year 2004	License # 1327	Rated Capacity ***** 83
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANCPH32F204109	Model Year 2002	License # 1190	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDXE45FX2HA28036	Model Year 2002	License # 613	Rated Capacity ***** 30
Chassis Make Ford	Body Make Other	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANCPH73F206995	Model Year 2003	License # 387	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1HVBGAAN3VA078031	Model Year 1997	License # 661	Rated Capacity ***** 84
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABNB7AOXF088604	Model Year 1999	License # 1060	Rated Capacity ***** 72
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANC SHBRF059991	Model Year 1994	License # 560	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDXE45FSHA73877	Model Year 2000	License # 1124	Rated Capacity ***** 16
Chassis Make Ford	Body Make Other	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANCSA2WF077661	Model Year 1998	License # 1006	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANCPH91F097999	Model Year 2001	License # 1120	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANCSH4TF070168	Model Year 1996	License # 869	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANCPHXVF091638	Model Year 2000	License # 1061	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 32 Missoula		District Name Frenchtown K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANCSH1VF073726	Model Year 1997	License # 963	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date